




**ALLEGATO 1**  
**DOCUMENTAZIONE FOTOGRAFICA AGGIORNATA (2019)**

Annotazioni descrittive	IMMAGINI DA SATELLITE
Planimetria generale dell'area	
Fabbricati A e B	
Fabbricati C e D	

Annotazioni descrittive	<b>EDIFICIO A</b>
<p>Fabbricato A facciata est: pannelli della copertura e del tamponamento in distacco</p> <p>Fabbricato A interno capannone: porzione della copertura mancante</p>	
<p>Fabbricato A, corpo basso</p> <p>Esterno: deterioramento dei pannelli di copertura in fibrocemento-amianto</p> <p>Interno: stato di deterioramento degli impianti interni</p>	
<p>Fabbricato A, corpo basso: perdita dall'impianto idrico ed il conseguente allagamento degli ambienti e la fuoriuscita dell'acqua verso l'esterno.</p> <p>Murature e pavimenti deteriorati</p>	

Annotazioni descrittive	<b>EDIFICIO A</b>	
<p>Fabbricato A: particolari opere in ferro intaccate dalla ruggine</p>		
<p>Fabbricato A: facciata sud; Scarico abusivo di macerie di provenienza sconosciuta</p> <p>Fabbricato A: facciata ovest; Scarico abusivo di macerie di provenienza sconosciuta; Portone in ferro completamente arrugginito</p>		
Annotazioni descrittive	<b>EDIFICIO B</b>	
<p>Fabbricato B: Esterno fronte sud alloggio custode. In primo piano trave perimetrale con ferri di armatura affioranti e arrugginiti; Vegetazione cresciuta sulla copertura piana dell'edificio</p>		

<p>Fabbricato B: Esterno/Interno, soletta di copertura deteriorata dalle infiltrazioni d'acqua</p>	 <p>The left photograph shows the exterior of a building with a brick wall and a concrete base. The roof structure is visible, showing signs of deterioration and water damage. The right photograph shows the interior of a room with a window and a ceiling that is heavily stained and peeling, indicating significant water damage and mold.</p>
--	---

<p>Annotazioni descrittive</p>	<p><b>EDIFICIO C</b></p>
<p>Fabbricato C Esterno fronte est ingresso al magazzino</p>	 <p>The photograph shows the exterior of a building with a rusted metal facade. A green metal railing is in the foreground, and there is some debris and vegetation in the area. The building appears to be in a state of disrepair.</p>

<p>Fabbricato C Interno: Struttura portante in legno deteriorata dall'umidità</p>		
---	---	--

Annotazioni descrittive	<b>EDIFICIO D</b>	
<p>Fabbricato D: Interno con tracce di bivacchi illegali</p>		
<p>Fabbricato D: Interno con vista sul locale danneggiato dall'incendio</p> <p>Esterno con materiali di dubbia provenienza (refurtiva?)</p>		

Annotazioni descrittive	<b>EDIFICIO E</b>
<p>Lato est: -Fabbricato E: Cabina ENEL -Cancello dell'ingresso principale</p>	 The image contains two photographs. The left photograph shows a tall, rectangular concrete tower with a flat roof and a small window near the top, partially covered by green ivy. The right photograph shows a blue metal gate with a lock, set against a brick building. Several signs are attached to the gate, including a yellow triangular warning sign with a lightning bolt, a red circular 'no entry' sign, and a blue circular sign with a white 'X'.

Annotazioni descrittive	<b>TERRENO</b>
<p>Terreno confinante con la massicciata ferroviaria: recinzione parzialmente divelta o inesistente</p>	 The photograph shows a railway embankment with a concrete path and a metal fence. The fence is partially broken or missing in places. In the background, there are trees and a large industrial building with a corrugated metal roof.

Cernusco sul Naviglio, 04/10/2019

Arch. Djordjevic' Hildegarde